

	F TECH 010	  <p>Certificat n° 2006101702</p>
	Version n°4 – 12.03.09 - Page 1 sur 18	
	RAPPORT ZAC	

**REPORT OF PARTICULAR CONTROL
OF DANOLINE TILES**

N ° 9 03 034 – DANOLINE A/S – KNAUF GROUP / 2 VER.0



CLIENT	Danoline A/S – KNAUF group To the attention of Erik IPSEN Klovermarksvej,6 DK 9500 HOBRO DENMARK
PRESTATION EFFECTUEE	From 09 th to 21 st April 2009
PAR	J. HERNANDEZ CERA-LABO ZI de la Montagne de l'Aspre 30150 ROQUEMAURE

Writing by
Name :
Date :
Signing :

Quality control
Name :
Date :
Signing :



I. CONCLUSIONS

A. CLASSIFICATION OF DANOLINE TILES

Tests		Norms	Criteria	Values	Conformity
Particle cleanliness class normal condition face		ISO 14644-1	ISO 5	ISO 5	Conform
Particle cleanliness class normal condition back		ISO 14644-1	ISO 5	ISO 5	Conform
Particle cleanliness class with unormal conditions	Vibrations face	ISO 14644-1	ISO 5	ISO 5	Conform
	Vibrations back	ISO 14644-1	ISO 5	ISO 5	Conform
	Damaged face	ISO 14644-1	ISO 5	ISO 6	Not conform
Kinetic of decontamination class		NF S 90-351	CP _(0,5) 10	CP _(0,5) 10	Conform

B. REMARKS

- Danoline tiles fulfil the requirements of zones 4 in particular control according to the norm NF S 90- 351.